



Village of Westmont

Purchase Order

PO Date: 2021-02-05

Page: 1 of 1

Bill To:

MUNICIPAL SERVICES
31 W QUINCY
WESTMONT, IL 60559

THIS NUMBER MUST APPEAR ON ALL INVOICES, PACKAGES AND SHIPPING PAPERS.

Purchase Order # **21201487**

Vendor:

Truck Country of Illinois, Inc
2099 Southpark Court
Dubuque, IA 52003

Ship To:

See Shipping Information Below

Vendor Number	Vendor Phone Number	Vendor Fax Number	Delivery Reference			
101141						
Item#	Description/PartNo	QTY	UOM	Unit Price	Extended Price	
1	2021 Freightliner 108SD 5 Ton 2021 Freightliner 108SD 5-Ton dump truck Replacing #100 GL Account: 2552525 - 57096 - 1GOV Ship To: MUNICIPAL SERVICES 31 W QUINCY WESTMONT, IL 60559	1.0	EACH	\$165,937.00	\$165,937.00	
					\$165,937.00	

By: Spencer Parkes
Authorized Signature

PO Total **\$165,937.00**

*All vendors must comply with applicable regulations of the Illinois Department of Human Rights.
 *This order is exempt from Federal Excise Tax under title 25 USCA, and from Illinois Sales Use and Service Taxes. E9997-4320-07.
 *Acceptance of this Purchase Order constitutes agreement by vendor that any action arising out of this Agreement may be commenced only in the State or Federal courts located in DuPage County and/or the Northern District of Illinois. The prevailing party shall have their attorney's fees and court costs paid by the losing party.
 *The Village of Westmont will process all bills in accordance with the Illinois Government Prompt Payment Act 50 ILCS 505.

**Westmont Public Works - Fleet Division
Vehicle Replacement Program
Purchase Summary**

Purchasing

P.O.# :
Year : 2021
Make : Freightliner
Model : 108SD
Vendor : Truck Country
VIN : N/A

Replacing

Dept./Div. : Street Dept.
Unit : #100
Year : 2006
Make : International
Model : 7400 Dump (5 Ton)
Miles : 28,077
Hours : 7,484
VIN : 1HTWDAAR06J304291

The proposed vehicle meets the recommendations of the Ad hoc Committee on Climate Change based on:

Fuel Economy (at least one MPG better than vehicle replaced).

Switch to Hybrid

E-85 Compatible

Bio-Diesel Compatible

Does not meet AHCCC recommendations

Specifications reviewed by Fleet Manager:


signature

Comments :

(Must be completed when replacement is for reasons outside of VRP definition/terms)

Replaced Due to age

Repair costs are getting to high